uEZGUI-EXP-DK
Product Change Notification Form

PCN Number: 20140708-01	Rev: 2.1	Date: 07/08/2014

Summary of Change: Change uEZGUI-EXP-DK BOM for incorrect capacitors on analog audio signal going into Wolfson Audio codec

Reason for Change: The first 25 prototype assemblies were loaded with incorrect C32 and C38 capacitor values which caused a very specific audio circuit option not to work correctly.

Detailed Description of Change: Change both C32 and C38 to 220pF. This corrects the DAC input into the Wolfson codec which will allow analog playback into the headphone connector when I^2S Audio is not utilized. Most use cases involve either using the I^2S Audio with Wolfson or direct DAC output to the onboard amplifier circuit. Therefore, this affected feature is only used in special configurations.

Products Affected:

Effected Product (Rev 2.0)	Recommended Replacement Product (Rev 2.1)
uEZGUI-EXP-DK	uEZGUI-EXP-DK

Availability of new revision stock at distributors:

Distributors will continue to sell through their existing available stock before filling customers' orders with stock of the new revision of the product.

Forecasted Key Dates and Milestones:

07/08/14 PCN Date, the date this document was released for distribution to customers and distributors.

07/08/14 Production Date for Recommended Replacement Product, the first date that production quantities of the replacement units will be available for customer order.

Reference Documents: https://www.teamfdi.com/product/uezgui-exp-dk/#documentation

1. uEZGUI-EXP-DK Brochure.pdf
2. uEZGUI-EXP-DK Quick Start Guide.pdf
3. uEZGUI-EXP-DK Users Manual.pdf
4. uEZGUI-EXP-DK_SCH_2.pdf
5. uEZGUI-EXP-DK Rev 2.1 ECO



FDI Contacts:

For additional information or details please contact any of our franchised Distributors including Avnet, Digi-Key and Mouser. Or contact the Product Team at FDI directly via email at support@teamfdi.com or via phone at 256-883-1240 or fax at 256-883-1241.