

uEZGUI-1788-70WVT

Product Change Notification Form

PCN Number: 20120330-01	Rev: 3.1	Date: 03/30/2012
--------------------------------	-----------------	-------------------------

Summary of Change: uEZGUI-1788-70WVT-BA change D4 from load to DNL

Reason for Change: This change is to support a key customer configuration using the standard uEZGUI.

Detailed Description of Change: D4 on the uEZGUI-1788-70WVT-BA is being changed to "Do-Not-Load". This particular diode had too high current leakage on the Real Time Clock (RTC). D4 can be re-loaded by a customer or an external diode can be connected through J10 (off board battery backup) to replicate the same or similar functionality.

Products Affected:

Effected Product (Rev 3.0)	Recommended Replacement Product (Rev 3.1)
uEZGUI-1788-70WVT	uEZGUI-1788-70WVT
uEZGUI-1788-70WVT-BA	uEZGUI-1788-70WVT-BA

Availability of new revision stock at distributors:

Distributors will continue to sell through their existing available stock before filling customers' orders with stock of the new revision of the product.

Forecasted Key Dates and Milestones:

03/30/12 PCN Date, the date this document was released for distribution to customers and distributors.

03/30/12 Production Date for Recommended Replacement Product, the first date that production quantities of the replacement units will be available for customer order.

Reference Documents: <https://www.teamfdi.com/product/uezgui-1788-70wvt/#documentation>

1. uEZGUI-1788-70WVT Brochure.pdf
2. uEZGUI-1788-70WVT Quick Start Guide.pdf
3. uEZGUI-1788-70WVT Users Manual.pdf
4. uEZGUI-1788-70WVT_SCH_3.pdf
5. uEZGUI-1788-70WVT Rev 3.1 ECO



FDI Contacts:

For additional information or details please contact any of our franchised Distributors including Avnet, Digi-Key and Mouser. Or contact the Product Team at FDI directly via email at support@teamfdi.com or via phone at 256-883-1240 or fax at 256-883-1241.